Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Drilling of borewell and erecting pump and Motor and providing MWS behind the police station at jalahalli (MWS)
2	Administration Approval & Date	JC/RRNZ/AS/2950/2013-14 Dtd.05-03-2014 by JC (RRNZ)
3	Technical Sanction Estimate No.& Date	EE/RRND/TS/11/2014-15 Dtd: 16-06-2014 by EE(RRND)
4	Estimate Amount	Rs.8.00 Lakhs
5	Job Code No.	016-14-000028
6	P-Code	P-2178
7	Agreement No & date	EE/RRND/AG.No./31/2014-15 Dtd.20-06-2014
8	Work order Number & Date	EE/RRND/Wo.No./31/2014-15 Dtd.20-06-2014
9	Contract Amount as per Agreement	Rs. 800,000/-
10	Bill Amount	Rs.8,87690 /- including KRIDL Charges
11	B.R. No. & Date	282/2014-15 Dtd: 31-7-2014
12	Agency	KRIDL, Bangaluru
13	M.B. Number & Page No. of Measurement recordes	1812/14-15 Pages 181120 to 181131 (Xerox Copy of MB)
14	Date of Inspection	1 – 1 – 2016
15	Enclosures	1) 2 Number of photos taken during inspection
16	Inspection Report	The above site has been Inspected by me along with the conserned person. It is observed that one bore hole has been drilled and is connected to the cystren for providing drinking water to the residents of the area. The bore hole is functioning. This has a reference to the Xerox copy of MB NO 1812

EE (RRND) RR Nagara Zone

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು

(R.Sathyanarayana)
Inspection Report officer,